



DIR- 455 Firmware Release Note

Firmware: v1.00B08

Hardware: A1

Date: 2009/09/07

Problems Resolved:

1. Rename the internal firmware version V1.00B08 into Hidden page.
2. A string error with BigPond. To dismiss this item.
3. The time does not be synchronized with Internet time server automatically
4. The time cannot be set manually -- remove the manual mode.
5. WAN Type PPTP/L2TP can't connect successfully to some servers.

Enhancements:

1. To press "Reboot Now" button, the main page of DIR-455 cannot be displayed automatically after rebooting--UI's modification, will extend rebooting time(45s-->50s)..
 2. Auto-Backup can still be saved if the Internet host field is empty. To add the notice into our UI.
 3. It might prompt a pop-up warning message as Server IP is empty.
 4. Remove the MAC address information in the status page when WAN type is 3G.
 5. There is no information about 3G Connection in the Support's description.
-