



DIR-600 Firmware Release Notes

Firmware: FW203WW

Hardware: Bx

Date: 2010/5/3

Note:

1. FW version is advanced to v2.03.

Problems Resolved:

1. Fix the issue that DIR-600 doesn't update the security settings in web UI when client is connected over WPS PIN method.
2. Fix the HNAP security issue that the malware "hnap0wn" can change the security setting of Administrator.

Enhancements:

None

Known Issues:

None