

M15 Firmware Release Notes

Firmware: v1.08

Hardware: A1

Date: August 22nd, 2023

Wi-Fi Country code support:

AU, BD, BR, CA, EG, EU, ID, IN, IT, KR, LA, MA, NA, RU, SG, SG1, TH, TW, US

DFS band support:

AU, BR, CA, EG, EU, IN, KR, MA, NA, SG, SG1, TH, TW, US

Problems Resolved:

- Fix security issue (IPv6 NAT, WPS pin code, default access LAN client allowed and support all security type under extender mode).
- SIP phone connection issue.

Enhancements:

- Improve operation mode (Extender, API issue).
- Support HT80 on ID country code.
- ETSI EN 303 645 compatible.

Known issues:

- Mesh nodes will show on client list sometimes.
 - Need to improve IPv6.
 - VPN service not worked on Android device. (Android OS does not support RSA encryption 2048-bit yet).
-
-

==END==